

Firmware Change Log for Industrial Security Router Series IE-SR-4GT

List of affected Router models:

Article name	Article number
IE-SR-4GT	2873910000
IE-SR-4GT-LTE/4G-EU	2873920000
IE-SR-4GT-LTE/4G-USEMEA	2873930000
IE-SR-4GT-M	2990450000
IE-SR-4GT-LTE/4G-USEMEA-M	2990440000

General Upgrade/Downgrade information:

Downgrades from version 2.2.2 or higher to version 2.1.2 or below are no longer possible on devices with cellular modems (2873920000, 2873930000, 2990440000) due to EN 18031-1 / RED compliance.

Before commissioning the device for the first time, we strongly recommend checking the installed firmware version and updating to the latest version, if a newer one is available. Please check and download the newest version from the Weidmüller website.

Upgrade to version 2.0.10 or higher is only possible from version 1.3.9. For Routers with versions < 1.3.9 first update to version 1.3.9 followed by a final update to latest version.

For downgrades from version 2.0.10 or higher to version 1.3.9 or below it is necessary to bring the router into compatibility mode. Refer to the manual to find out how to activate compatibility mode.

Version 2.2.6, Build number 181926.

Release date: January 5, 2026

Bug Fixes:

- Improved error message display for password changes in the Configuration Wizard and Users page. Error messages are now properly shown when passwords do not match or validation fails.
- The OpenVPN Client will not reject any IPv6 settings and continue with the IPv4 settings if a OpenVPN server pushes both IP settings.
- Previously, users with restricted write permissions needed full write access to all settings on a page in order to make any changes. This has been improved for the Date & Time page: input fields without write permission are now disabled, while the remaining fields can still be modified.
- The 1:1 NAT functionality for u-link VPN connections has been fully restored. Earlier firmware versions had unintentionally removed both configuration variables and the related web interface elements, which made the feature unavailable. Now all components have been reintroduced and 1:1 NAT operation is fully functional again.
- IP forwarding rules configured with IP-alias addresses (Local IP field specified) were not applied directly; they only became active after saving the configuration and rebooting in older Versions. This is fixed now.
- Improved error handling for certificate uploads. Invalid or unsupported file formats are now correctly detected and reported.
- Updated the password strength help text to clearly describe all password policy requirements, improving usability and security transparency for users.
- Restored the display of current I/O pin states on the I/O page.
- Improved handling of WWH protocol switching for u-link (WWHv1 / WWHv3). Switching between protocol versions is now processed more reliably, ensuring stable reconnection and consistent VPN operation.
- Fixed a JavaScript error on the USB access configuration page that previously prevented applying settings. The page now operates as expected.
- Resolved an issue where the Remote Capture service (Port 2002) was not starting correctly after being enabled. The service now operates as expected.
- When importing a cf2 file created with the exact same software version, the routers rules cache was not rebuilt, which could leave stale data and cause incorrect packet filtering until the filter configuration is changed or the device is switched to a different software version. The cache is a local copy of the active Linux kernel rules, used to speed up boot, and it is normally refreshed when changes are applied or firmware versions change. In this bug scenario, the import skipped regeneration, leaving data from a previous configuration. In 2.2.3, the cache will always be regenerated on import to avoid the issue. Until then, clicking Apply and then Save, or creating the cf2 file from an older firmware version, ensures a correct cache.

- The rule name input field now enforces the backend's 16-character limit, preventing unnecessary configuration errors and improving usability.
- Added a clear warning message to prevent unintentional lockout when disabling all remote access interfaces.
- Fixed a bug where the hostname was not sent correctly in a DHCP request.

Feature updates:

- The Audit-Log functionality has been significantly extended. The system now records a comprehensive range of hardware and network-related events, including USB device connections, Ethernet link changes, VPN key or CUT signal transitions, and u-link VPN connection states. These enhancements improve transparency and traceability for system administrators and are fully integrated into the web interface for clear and structured visualization of all relevant Audit-Log entries.
- The Audit Log system will now log changes of date and time and jumps in a new section "System".
- The Audit Log can now be forwarded to a Remote Syslog Server. Use the Eventlog Configuration web page to configure this function.
- The firmware now allows uploading a custom CA certificate including its private key. This enables operators to integrate the device into an existing PKI or OT-wide trust hierarchy instead of relying on the automatically generated self-signed CA. When a custom CA is provided, the device automatically issues its HTTPS server certificate from this CA, including the current DNS hostname and all assigned IP addresses as X.509 Subject Alternative Names (SANs). If the uploaded CA is a subordinate CA of a higher-level organizational root, multiple devices within the same OT environment can share the same trust anchor. This significantly improves interoperability and security by enabling mutual trust between systems and simplifying certificate management across installations.
- A strong password policy is now enforced by default when the device is reset or started with factory defaults. Existing installations are not affected by updates.
- The web interface now includes security headers in its HTTP responses to improve browser protection. These headers help prevent content type spoofing and unauthorized embedding of the web interface, increasing resilience against common web-based attack vectors. The options set are: "X-Frame-Options: SAMEORIGIN" and " X-Content-Type-Options: nosniff".
- Introduced a session limit to prevent excessive concurrent logins. This improves system stability and protects memory resources during intensive operation.
- Allow dynamic port forwarding on u-link with WWH3.
- Added Secure NTP (NTS-KE) for Client and Server/Relay operations.
- OpenVPN: Allow minimum version TLS 1.3 from now on.

Version 2.2.3, Build number 180042.**Release date: September 16, 2025****Bug Fixes:**

- IP forwarding rules configured with IP-alias addresses ("Local IP" field specified) were not applied directly; they only became active after saving the configuration and rebooting.
- When importing a cf2 file created with the same software version, the firewall rules cache was not rebuilt, which could leave stale data and cause incorrect packet filtering until the filter configuration is changed or the device is switched to a different software version. The cache is a local copy of the active Linux kernel rules, used to speed up boot, and it's normally refreshed when changes are applied or firmware versions change. In this bug scenario, the import skipped regeneration, leaving data from a previous configuration. In 2.2.3, the cache will always be regenerated on import to avoid the issue. Until then, clicking Apply and then Save, or creating the cf2 file from an older firmware version, ensures a correct cache.

Feature updates:

- By default, the password strength policy is now enforced on all newly deployed devices as well as on devices that have been reset to factory defaults. Consequently, the configuration wizard prevents completing setup with a weak password.
- The Web Interface is now using "Content Security Policy" options in the HTTP header as far as possible.

Version 2.2.2, Build number 179543.**Release date: August 18, 2025****Bug Fixes:**

- Fixed a regression in the Layer 2 Packet Filter introduced in version 2.0.10. Manual TCP Flags (field name: "state") filter rules at Layer 2 were not accepted and were inadvertently removed during updates from version 1.3.9 to 2.x.y.
- A regression bug introduced in version 2.0.10 that affected stateful ICMP rules in the Packet Filter was fixed. These rules were unintentionally removed by a new database consistency check during update. ICMP rules can be created using three methods: "automatic", "stateful", and "manual" — only the "stateful" method was affected by this issue. This has now been fixed. Note: If you previously used stateful ICMP rules, please verify they are still present and valid after updating.
- The Filter Wizard database once again supports names up to 32 characters for background processes such as updates from older versions or the import of settings via API. Therefore, the upload of older

configurations will no longer fail because of longer names. The user interface will continue to enforce a 14-character limit due to internal Linux kernel topics.

- When the Remote Capture Service was enabled, it started correctly, but the Web Interface UI failed to return to its normal state after clicking the Apply button. This regression bug was introduced with version 2.0.10.
- Fixed a regression affecting the diagnostic data download feature. After clicking the "Download" button, the interface became unresponsive, and the button remained disabled. This issue was introduced in firmware version 2.1.0. The download function now works as intended.
- The OpenVPN Server configuration table for clients was fixed. There was no clear error message if no password was supplied, this could lead to the impression that it is impossible to add an entry into the table. The UI was fixed to enforce the password.
- No message was displayed regarding saving when a user account was deleted.

Feature updates:

- Added a fail to ban mechanism based on the source IP address. By default, a ban time of 60 seconds after 10 wrong password attempts from a same IP is active after software update to 2.2.0. The ban is issued on the source IP independent of the tried username. The login ban behavior is configurable.
- A new Denial-of-Service (DoS) protection mechanism has been implemented. This enhancement safeguards the router against local network DoS attacks, particularly on Ethernet segments, ensuring greater reliability and resilience during device discovery and configuration.
- Furthermore, the web interface is now equipped with a DoS protection mechanism which will limit the TCP data upload transfer and packet rate
- Added a Network Monitoring Mechanism which will detect ARP cache poisoning attacks to the device's own IP and report them as Anomaly in the Audit system.
- Added auditability of configuration changes.
- Added auditability of Packet Filter matches. The logging is limited to one message for each rule per minute.
- WWH 3.0 protocol version can now be enabled for early adopters.
- Enhanced SNMPv3 Support:
 - New cryptographic hash algorithms have been added, now supporting up to SHA-512.
 - SNMPv3 traps have been fixed and are now functioning correctly. The SNMP Engine ID can now be configured manually as well.
 - User synchronization: SNMPv3 usernames and their write permissions are now synchronized with the main user database. This reflects the requirements of upcoming IEC62443 4-2 functional requirements. However, due to differing password algorithm requirements, SNMPv3 service passwords must be configured separately.
 - Security Note: SNMPv3 user passwords are stored in clear text on the device, as required by the SNMPv3 authentication algorithm.
 - The SNMP service (UDP Port 161) can now be restricted to selected interfaces.
 - The password policy and lifetime mechanisms are not enforced to the SNMPv3 passwords to keep update compatibility.
- The Status LED will now signal the new commissioning mode (Use of the Config Wizard) in case of factory default settings. Please note that the device will no longer forward IP traffic between the different network interfaces LAN/WAN or ETH1/ETH2-4 if it is not yet configured and running in commissioning mode.
- The NTP server interface and the Remote Capture Server interface can now be configured with a network interface input filter.
- When initially setting up the router or after a factory reset, a secure new password must be assigned.

Features disabled:

- SNMPv1 and v2 have been removed to comply with the upcoming EN18031-1/RED regulatory standard. When updating or importing older settings that contain SNMP configurations:
 - SNMPv2 settings will be automatically removed and disabled.
 - SNMPv3 usernames that do not exist in the main user database will be created automatically with randomly generated passwords. These will be assigned read-only permissions in the permissions database or write-all permissions for the SNMP read/write user. This reflects the behavior of previous versions.
 - SNMPv3 usernames already existing in the user database will be enabled if they were previously disabled. Their SNMPv3 service password will be set to a new random value. No changes will be made to their existing user account permissions.
 - All network interfaces will listen for SNMPv3 requests if the service was enabled.
 - SNMP Traps will get disabled on update and must be reconfigured.**

Version 2.1.2, Build number 177017.**Release date: May 15, 2025****Bug Fixes:**

- Addressed several usability bugs on the newly introduced Ethernet Bonding web interface, first released in version 2.1.1.
- Resolved an issue where packet filter rules using negated interfaces (e.g., != WAN) were mishandled. This regression, introduced in version 2.0.10, caused such rules to be incorrectly removed during updates and prevented them from being added through the configuration interface.
- Fixed Login via u-link Web Access to the device itself, which was broken due to a regression bug starting with version 2.1.0.
- Fixed:** Restored u-link dynamic forwarding for VNC and other protocols when the device operates in legacy MD5 password mode. This functionality was previously broken due to a regression introduced in version 2.1.0.
- Improved IPsec certificate-based ID handling which could lead to incompatibilities with other vendors.

Feature updates:

- Added the possibility to display a custom text on the login screen

Version 2.1.1, Build number 174444.**Release date: Apr 22, 2025****Bug Fixes:**

- The new password policy and password storage migration buttons on the User Accounts web page have been redesigned for improved clarity and ease of use.
- In versions prior to 2.0.10, it was possible to disable HTTPS entirely. However, starting from version 2.0.10, HTTPS is mandatory as it is the only supported interface. Devices that had HTTPS disabled in previous versions and were upgraded to 2.0.10 or higher experienced a complete loss of web UI access—neither HTTP nor HTTPS was available due to the old setting preventing HTTPS from being enabled. To prevent this issue, the option to disable HTTPS has been removed from the internal configuration.
- Resolved a regression bug introduced in versions 2.0.10 of the Filter Wizard that prevented users from adding new rules to existing rule sets. While newly created rule sets appeared in the UI, they were not actually applied and would disappear after a reboot if more than 14 characters have been used for the ruleset name.
- Fixed u-link routing issue affecting 1:1 NAT configurations, which was introduced by a regression bug in version 2.0.10.

Feature updates:

- Enhanced IPsec Policy Configuration. Feature: Allow 0.0.0.0/0 as the IPsec remote subnet for IPsec policies. Note: When configuring an IPsec policy with 0.0.0.0/0 as the remote subnet, ensure you add appropriate static IP routes targeting the IPsec device. These routes are necessary to direct the traffic into the IPsec tunnel for this special case.
- USB IP Device Server: Added USBIP device server functionality, allowing attached USB devices to be shared over the network. Compatible clients include standard Linux USBIP clients and commercial USBIP solutions particularly useful for Windows clients.
- Ethernet Bonding: A new feature has been added to enable network link bonding on the router. This supports both IEEE 802.3ad LACP (Link Aggregation Control Protocol) and active-backup modes. You can configure multiple interfaces on the device's WAN Ethernet switch for bandwidth aggregation or to create redundant uplinks for improved link failure resilience.
- The IPsec configuration web page has been enhanced to provide a clearer and more intuitive DH group selection process.
- Added the ability to specify the maximum password reuse limit to ensure compliance with IEC 62443-4-2 FR 1.
- Integration of a new Security Audit system. In the first step it will record all failed and successful logins into the administrative web interface and APIs in a persistent internal database. The feature is designed to comply with IEC62443 4-2 CR 2.8, CR 2.9 and CR 2.10.
- The password lifetime can now be configured according to IEC62443 4-2 CR 1.7.
- Network interfaces that obtain their IP address via DHCP will now perform a DHCP refresh when the Ethernet link is disconnected and reconnected. If the interfaces are part of an internal Ethernet bridge, this refresh will only occur when all connected interfaces lose their Ethernet link.
- Added the possibility to hide or show menu entries for specific users in the web interface

Version 2.0.10, Build number 174444.

Release date: Jan 16, 2025

Bug Fixes:

- Fixed WWAN issue on system startup where the WWAN modem was enabled for permanent connection without a SIM card inserted. This caused a memory leak, resulting in a non-functional WWAN connection even after inserting a SIM card and led to high CPU usage.
- Configurations in which the device functions as an OpenVPN server were affected by a regression error. The IP port forwarding no longer worked correctly since the version 1.3.9.
- Products with an integrated Fibocom NL668 WWAN modem experienced issues selecting the correct profile when the SIM card was shipped with a custom profile (including settings like APN, etc.). Affected systems would never go online.
- Fixed a bug affecting the behavior of external digital inputs and the packet filter. Rules that depended on the state of the digital input were not activated during startup because the input state was not evaluated initially. The rules only activated or deactivated after a change in the input state, based on the configuration. This issue was introduced in version 1.0.6.
- In individual setups with the Router, Ethernet problems were observed, which manifested themselves in infrequent 1-10 second interruptions of Ethernet switch data traffic on ports LAN1-LAN3. In the event of a fault, the Ethernet link was not affected and still displayed a good link. The problem could be solved by selected parameter changes of the internal switch chip.
- Errors in connection with the cellular modem have been fixed. If the cellular modem is activated but no SIM card is inserted, there were connection problems with u-link, although u-link is operated via Ethernet in this case. Furthermore, the automatic reset of the cell modem to automatically find a newly inserted SIM card is now stopped after three attempts and then only retried every 24 hours.
- Removed adsdppd debug log messages from Eventlog.
- The IPsec aggressive mode has not worked properly. This behavior has now been fixed.
- The WWAN LED could remain active after a reboot or if the modem was configured to go online and the firewall device was later reset to factory defaults. In such cases, the WWAN LED status did not correctly reflect the firewall's WWAN online/offline state. This bug was fixed.

Feature updates:

- The firmware update page on the device's web interface has been enhanced. Now, there are two methods to check for updates. The device will first attempt to contact the update server directly. If this fails, it will then use the user's browser as a fallback to relay the contact, verify, and update the device firmware. Previously, the device itself required an internet connection for this process.
- USB sticks formatted with the EXT4 filesystem can now be used for firmware updates and settings file uploads. Additionally, a race condition has been resolved, which previously could cause the USB stick not to be processed during bootup if it was too slow.
- New self-signed HTTPS certificates: The device will generate a self-signed device Certificate Authority (CA) from which all HTTPS web server certificates will be derived. This device CA will be created once and will remain valid even after a factory reset. The derived web server certificates will be updated whenever there are changes to the static IP or hostname, and these certificates will include this updated information.
- We are introducing a new implementation for authentication. This update employs sessions and Argon2 hashing, replacing the previous use of MD5 hashes and HTTP digest authentication. However, the previous method can still be enabled for compatibility purposes. As a result of these changes, users will see a completely new login page and a revised logout mechanism, including a session timeout set to 300 seconds of inactivity.
- Improved syslog reporting of successful and failed logins on the device web interface or APIs.
- The OpenVPN server with RADIUS authentication, which had been previously removed, has now been reintegrated.
- The range of supported IPsec PSK values has been expanded. You can now configure PSKs as Base64-encoded binary values, Hex values, or regular strings with all special characters supported by the StrongSwan backend.

New webpages:

- The packet filter has now a new status page with traffic graphs for each filter rule.
- The web interface of the product now additionally lists the OSS components and licenses currently included in the product.
- Firmware updates or settings files can be imported via the USB port of the devices. This function can now also be deactivated on a new subpage in the web interface. If the storage of Syslog messages on the USB stick is disabled as well, then the USB stick will remain completely unmounted for improved security.

Features disabled:

- The Web Interface of the device is now reachable by HTTPS only for security reasons. The firewall web interface will automatically redirect HTTP requests to HTTPS, ensuring secure web access. However, if your previous configuration used HTTP (port 80), this will now be redirected to HTTPS (port 443). All

HTTP requests from the allowed interfaces will be automatically redirected to HTTPS if HTTP is allowed on the Web access page. If HTTP is disabled on the Web access page the redirect is disabled.

- The classic HTTP API is deactivated with the default settings mode for security reasons. The classic HTTP API is still available in compatibility mode. Refer to the manual to find out how to activate compatibility mode. For security reasons, it is recommended to switch to the HTTPS API.

Version 1.3.9, Build number 163577.

Release date: Feb 06, 2024

Bug Fixes:

- The following features had a concurrence issue starting with version 1.3.5: U-link route push on devices with LTE modems, remote capture service, WWAN channel scan and VPN UP blink service. Therefore, only one of the features could work well at a time. The issue is fixed with this version.
- Fixed a possible memory leak that could lead to a shortage of free RAM after an uptime of more than 200 days.
- A bug has been fixed that, under certain circumstances, could cause TCP streams directed to other IP addresses neighboring on a switch to be forwarded through the device. Therefore, setups with IP settings via DHCP and simultaneous TCP port forwards on these network interfaces are recommended to update to this version.

Version 1.3.7, Build number 160694.

Release date: Dec 07, 2023

Bug Fixes:

- The remote syslog was not working correctly after a system reboot.
- The PPPoE settings on the web interface had been invisible due to a regression bug introduced with IE-SR-4GT V1.3.4.
- Date and Time settings did not offer a date later than 2023
- Fix SMS service on IE-SR-4GT-LTE/4G-USEMEA versions with SierraWireless EM7455 modems.
- Fixed the VPNUP I/O signal
- Fixed the VPN LED / VPN UP configuration drop down. The IPsec option was lost in the drop down due to a regression bug. This has been fixed.

Feature updates:

- Added the possibility to upload a WWAN modem update in the device web interface. Use the web interface and navigate to: System -> Software Update -> Tab:WWAN. Please contact Weidmüller support in case a firmware file is needed.
- Enable the SMS features and the WWAN network scan for the IE-SR-4GT-LTE/4G-EU model with Fibocom NL668EAU modem. Additionally the mobile phone number and ICCID of the SIM card have been added to the WWAN status page for all modems.

Version 1.3.4, Build number 157906.

Release date: Sep 25, 2023

Bug Fixes:

- Config files from IE-SR-4GT-LTE could not be loaded into an IE-SR-4GT-LAN and vice versa. This has been fixed.
- U-link remote network routes will now be automatically configured for network interfaces using DHCP or Fallback IP assignment when the device is in 'Transparent Bridge' mode. Previously all network interfaces in these modes were skipped. Please note that u-link does not support changing network routes while the VPN connection is established!
- A regression bug in the web UI, specifically concerning the enabling of SNAT on interfaces with DHCP IP assignment, has been fixed.
- Fixed the logging of authentication failures on the web interface.
- Increased the maximum length of Eventlog entries as some lines were cut after 256 characters.
- The automatic transmission of new or modified static routes to u-link was not functioning as intended. It necessitated a manual u-link VPN restart on the device. With the current update, the u-link VPN on the device will now automatically restart when a change or addition is made to a static route along with u-link synchronization. As a result, the new route will promptly become visible to the u-link server. It's important to note that any u-link VPN connected users must still perform a restart on their VPN endpoints to access the newly added routes.
- OpenVPN client: Static routes with a gateway on the OpenVPN interface were not restored during the VPN reconnect, but only during the initial connection until it is lost. This has been fixed.

Feature updates:

- Update of numerous internal open source software components.
- The Wireshark Remote Capture service "rpcapd" has been added.
- The configuration variables for controlling u-link VPN are added to the Permission list.

Version 1.3.3, Build number 156153.**Release date: Aug 04, 2023****Bug Fixes:**

- If the IP assignment of the WAN interface was changed from DHCP to static and the "Gateway via DHCP" option was activated at the same time, then the gateway field in the IP configuration was deactivated and it was not possible to make a gateway entry. This is fixed now.
- Improved the initial connection time and the time needed for reconnection after a link loss for the u-link WWH connections.
- The DNS proxy and the DHCP server must be configured separately since version 1.3.0. This separation was incomplete. The DNS proxy was running automatically in the background if the DHCP server was enabled on a certain interface. This has been fixed. Existing configurations will get updated on firmware update as follows: The DNS proxy will be enabled on all DHCP server interfaces if it was off before.

Feature updates:

- Allow the configuration of an NTP relay which will always step its clock directly to the NTP servers time. For example, if the time on the uplink NTP server changes spontaneously with a large value even during runtime. The option is named "Allow spontaneous NTP time step" and can be found at "Date & time". It is disabled by default.
- The devices can now use the u-link WWH connection to synchronize their date and time to the u-link server. To enable the feature, activate "World-wide heartbeat time synchronization" on the Date & Time configuration page. The time will be synced if it differs more than 60 seconds from the server. The synchronization is done inline in the WWH protocol and therefore the interval is dynamic at ~60-200 seconds.

Version 1.3.2, Build number 154727.**Release date: Jun 13, 2023****Bug Fixes:**

- Network groups: The string length of the newly introduced DNS based entries has been increased.
- New packet filter rules were not applied or saved. This regression bug was introduced with version 1.3.1.

Feature updates:

- The SNMP function was added to all three router models.

Version 1.3.1, Build number 154292.**Release date: May 30, 2023****Bug Fixes:**

- In the IP router (extended) mode, the error was fixed that the default gateway could only be entered after pressing Apply once.
- On the System State page, the u-link references in the Interface State table have been corrected.
- Incorrect entries in tables are now intercepted via an error message. No error message appeared in the previous versions 1.2.0 and 1.2.1.
- Fixed problems with the NTP relay and Siemens PLCs, the ntpd server process reported "Rate Limit reached" in the Eventlog and stopped working. This has been fixed.
- Improved NTP client behavior on power up. In some cases, it took days to synchronize the clock if there was a dynamic IP setting on the uplink like DHCP or WWAN. This issue has been resolved.
- In the Packet filter layer 3 section, the rules were incorrectly numbered, which has been fixed in this version.
- In versions 1.2.0 and 1.2.1 it could happen that WWAN PIN, MNC, and MCC and smartcard PIN settings with leading zeroes became invalid. This has been fixed in the current version, but there is a possibility that these codes must be entered again.

Feature updates:

- Added the possibility to enable debug logs for the DHCP service.
- There is a new diagnostics download. It contains more internal details for Weidmüller support, is stored in plain text and does not contain any credentials or other confidential data from the configuration.
- The HTTP/S and the DNS proxy access filter network interfaces have changed from physical mapping to interfaces with IP address only. Old configurations will continue to work as before, but on reconfiguration all pure Ethernet interface on bridges will get removed.
- Introduce DNS based packet filter. The already existent network groups can now be used with DNS host and domain names. In combination with integrated DNS proxy every DNS lookup will get synchronized with the packet filter IP addresses.

Version 1.2.1, Build number 151699.**Release date: Apr 27, 2023****Bug Fixes:**

- The Permissions web page did not allow to remove checked elements due to a regression bug introduced with version 1.2.0.

- Fixed a regression bug regarding transparent bridge mode on the device web interface introduced with version 1.2.0. It was not possible to change the IP address due to a Java Script exception.
- The Permissions for the filter wizard were not controllable due to a regression bug introduced with version 1.2.0.
- Fixed a regression bug which prevented devices with u-link VPN or SCM memory cards to load and apply a cf2 settings file generated with the firmware version 1.2.0.
- The HTTP API (get.php) did respond with wrong multiline formating on "statuslong" calls due to a regression bug introduced with version 1.2.0.

Version 1.2.0, Build number 150462.**Release date: Apr 13, 2023****Bug Fixes:**

- Fix DHCP server web interface page. It was not possible to disable the DHCP server using the web page once it had been enabled.
- More user-friendly configuration of the setup wizard regarding date and time selection (Web menu)

Feature updates:

- Cumulative update of integrated open-source software components.
- The WAN port can now be configured to use PPPoE either with or without an additional VLAN tag.
- Log IP changes on WWAN interfaces in the Eventlog
-

Version 1.1.6, Build number 148055.**Release date: Jan 18, 2023****Bug Fixes:**

- WWAN connectivity was permanently interrupted on devices with EM7455 in cases of spontaneous resets of the integrated EM7455 WWAN modem. This problem was introduced with 1.1.5.

Version 1.1.5, Build number 147499.**Release date: Jan 02, 2023****Initial Release**