

## Firmware release notes of BasicLine Industrial Wireless devices

### Affected models:

Device name	Article No.
IE-WL-BL-AP-CL-EU	2536600000
IE-WLT-BL-AP-CL-EU	2536650000
IE-WL-BL-AP-CL-US	2536660000
IE-WLT-BL-AP-CL-US	2536670000

**Version 1.26.2 Build 25081512 (RED-DA compliant)**

**Released: September 2025**

### New Features:

- Added a firmware signature-verification mechanism.
- Added support for the Wi-Fi Auth/Assoc timeout setting.
- Added support for AP-Based Connection Management.
- Added support for Gratuitous ARP.
- Added support for Jumbo Frame (MTU).
- Added support for Wireless Link Health Check (AP).
- Support all channels and 11 channels for Client-based Turbo Roaming channel scanning.
- Added support for Wi-Fi Remote Connection Check.
- Added support for client isolation in AP mode.
- Added an option to allow the use of special characters.
- Added an option to configure password encryption.
- Added an option to configure the N multicast rate.
- Added an option to configure the HTTP/HTTPS web port.
- Function to enable/disable SSL Certificates
- Function to configure the 3rd SNMP trap receiver.
- Added an option to keep wireless enabled when resetting the IE-WL-BL-AP-CL back to factory default settings.
- Added Indoor/outdoor channel list option.
- Added an option to show the PSK password in clear text.
- Web certificate support.
- Added an option to configure indoor/outdoor.
- Support Management Frame Encryption.
- Support the Quick Setup wizard.
- Support Wi-Fi certificate function.
- Support the Static MAC clone function.
- Support the Locate Device function

### Enhancements:

- Added the CPU and memory usage SNMP node.
- Supports WLAN system log version 2.
- WPA supplicant supports TLS v1.2.
- Supports bridge status via SNMP.
- Devices will record a system log entry if an invalid configuration setting is reset to the default value.
- Enhance system stability.
- Enhance compatibility with other brands.

### Bug Fixes/ Security Patches:

- [CVE-2023-52160] vulnerability.
- [CVE-2017-17562] vulnerability.
- Unauthenticated HTML/JS Injection (Stored XSS) into a web page.
- Simple bug fixes, security updates, and performance improvements.

**Changes:**

- Users are now required to change the default password when logging in to the web UI or CLI for the first time.
- Added a config check to ensure the UDP socket mode port range is set within 0 to 9999.
- Changed several names of SNMP OID.
- Changed the default multicast rate value according to the selected RF type.
- Changed the fixed rate list according to the selected RF type.
- Changed the management frame rate according to the selected RF type.
- Increased MAC/IP/Port filter entries up to 60.
- Adjusted the Wi-Fi signal level LED.
- The initial network IP is set to 169.254.0.1 before the DHCP server assigns an IP address for the first time.
- Changed the range for roaming threshold and AP candidate threshold from 5-40 to 5-60.
- Changed the UI field name "Signal Strength" to "Signal Level" on the wireless status page.
- The open "wireless interface" is now disabled by default.
- TELNET is now disabled by default.
- HTTP is disabled, and HTTPS is enabled by default.

**Notes:**

- This firmware is compliant with FOSS license requirements.
- This firmware complies with the EU RED-DA cybersecurity requirements (EN 18031-1:2024) related to RED Article 3.3(d) for products with connectivity functions that must prevent unauthorized access and misuse of data.
- For security reasons, a firmware signature mechanism was added to firmware v1.26.2. As a result, when uploading firmware in v1.26.2 or higher, you must upload a ZIP file that includes both the firmware file (.rom) and signature file (.sig). When upgrading to v1.26.2, you only need to upload the firmware file (.rom).

**Version 1.16.21 Build 21010513**

**Released: June 2021**

**Bug Fixes:**

- Unable to establish a Wi-Fi connection with APs that support IEEE 802.11r

**Security Patches:**

- CVE-2021-33528: Improper system access as a higher privilege user. An attacker can send commands while authenticated as a low privilege user to trigger this vulnerability
- CVE-2021-33529: Exploitable hard-coded cryptographic key allows for the decryption of captured traffic
- CVE-2021-33530/CVE-2021-33532/CVE-2021-33533/CVE-2021-33534: Improper Neutralization of special elements used in an OS command
- CVE-2021-33531: Exploitable hard-coded credentials
- CVE-2021-33535: Buffer copy without checking size of Input may cause remote code execution
- CVE-2021-33536: An attacker can send a crafted packet and cause denial-of-service of the device
- CVE-2021-33537: Stack-based buffer overflow
- CVE-2021-33538: Improper remote shell access to the device. An attacker can send commands while authenticated as a low privilege user to trigger this vulnerability.
- CVE-2021-33539: An exploitable authentication bypass vulnerability. An attacker can trigger authentication bypass on specially configured device.

**Version 1.16.18 Build 18081617**

**Released: September 2018**

**Bug Fixes:**

- Site Survey crashes after changing Operation Mode from Access Point to Client

**Version 1.16.2 Build 18030716**

**Released: April 2018**

- First release