

Firmware release notes of ValueLine Industrial Wireless devices

Affected models:

Device name	Article No.
IE-WL-VL-AP-BR-CL-EU	2536680000
IE-WLT-VL-AP-BR-CL-EU	2536690000
IE-WL-VL-AP-BR-CL-US	2536700000
IE-WLT-VL-AP-BR-CL-US	2536710000

Version 1.20.2 Build 25081511 (RED-DA compliant)

Released: September 2025

New Features:

- Added a firmware signature-verification mechanism.
- Added support for the Wi-Fi Auth/Assoc timeout setting.
- Added support for AP-Based Connection Management.
- Added support for Gratuitous ARP.
- Added support for Jumbo Frame (MTU).
- Added support for Wireless Link Health Check (AP).
- Support all channels and 11 channels for Client-based Turbo Roaming channel scanning.
- Added support for Wi-Fi Remote Connection Check.
- Added support for client isolation in AP mode.
- Added an option to allow the use of special characters.
- Added an option to configure password encryption.
- Added an option to configure the N multicast rate.
- Added an option to configure the HTTP/HTTPS web port.
- Function to enable/disable SSL Certificates
- Function to configure the 3rd SNMP trap receiver.
- Added an option to keep wireless enabled when resetting the IE-WL-VL-AP-BR-CL back to factory default settings.
- Added Indoor/outdoor channel list option.
- Added an option to show the PSK password in clear text.
- Web certificate support.
- Added an option to configure indoor/outdoor.

Enhancements:

- Added the CPU and memory usage SNMP node.
- Supports WLAN system log version 2.
- WPA supplicant supports TLS v1.2.
- Supports bridge status via SNMP.
- Devices will record a system log entry if an invalid configuration setting is reset to the default value.
- Enhance system stability.
- Enhance compatibility with other brands.

Bug Fixes/ Security Patches:

- [CVE-2023-52160] vulnerability.
- [CVE-2017-17562] vulnerability.
- Unauthenticated HTML/JS Injection (Stored XSS) into a web page.
- Simple bug fixes, security updates, and performance improvements.

Changes:

- Users are now required to change the default password when logging in to the web UI or CLI for the first time.
- Added a config check to ensure the UDP socket mode port range is set within 0 to 9999.
- Changed several names of SNMP OID.
- Changed the default multicast rate value according to the selected RF type.
- Changed the fixed rate list according to the selected RF type.
- Changed the management frame rate according to the selected RF type.
- Increased MAC/IP/Port filter entries up to 60.
- Adjusted the Wi-Fi signal level LED.
- The initial network IP is set to 169.254.0.1 before the DHCP server assigns an IP address for the first time.
- Changed the range for roaming threshold and AP candidate threshold from 5-40 to 5-60.
- Changed the UI field name "Signal Strength" to "Signal Level" on the wireless status page.
- The open "wireless interface" is now disabled by default.
- TELNET is now disabled by default.
- HTTP is disabled, and HTTPS is enabled by default.

Notes:

- This firmware is compliant with FOSS license requirements.
- This firmware complies with the EU RED-DA cybersecurity requirements (EN 18031-1:2024) related to RED Article 3.3(d) for products with connectivity functions that must prevent unauthorized access and misuse of data.
- For security reasons, a firmware signature mechanism was added to firmware v1.20.2. As a result, when uploading firmware in v1.20.2 or higher, you must upload a ZIP file that includes both the firmware file (.rom) and signature file (.sig). When upgrading to v1.20.2, you only need to upload the firmware file (.rom).

Version 1.11.13 Build 21010513

Released: June 2021

Bug Fixes:

- Unable to establish a Wi-Fi connection with APs that support IEEE 802.11r

Security Patches:

- CVE-2021-33528: Improper system access as a higher privilege user. An attacker can send commands while authenticated as a low privilege user to trigger this vulnerability
- CVE-2021-33529: Exploitable hard-coded cryptographic key allows for the decryption of captured traffic
- CVE-2021-33530/CVE-2021-33532/CVE-2021-33533/CVE-2021-33534: Improper Neutralization of special elements used in an OS command
- CVE-2021-33531: Exploitable hard-coded credentials
- CVE-2021-33535: Buffer copy without checking size of Input may cause remote code execution
- CVE-2021-33536: An attacker can send a crafted packet and cause denial-of-service of the device
- CVE-2021-33537: Stack-based buffer overflow
- CVE-2021-33538: Improper remote shell access to the device. An attacker can send commands while authenticated as a low privilege user to trigger this vulnerability.
- CVE-2021-33539: An exploitable authentication bypass vulnerability. An attacker can trigger authentication bypass on specially configured device.

Version 1.11.10 Build 18122616

Released: January 2020

Bug Fixes:

- Abnormal behaviour where DFS does not operate as expected
- Abnormal roaming handoff time if MAC clone enabled
- Device reboots if received abnormal beacon which format does not follow standard IEEE.
- Error handler for abnormal Wi-Fi packets does not work
- Static route of WLAN interface does not work if it applies DHCP client in Client-Router mode

Version 1.11.2 Build 18082313

Released: September 2018

Bug Fixes:

- Site Survey crashes after changing Operation Mode from Access Point to Client

New Features:

- Support for WDS-mode (Wireless Distribution System)

Note: Limitations when using WDS-mode:

- When selecting RF types G/N Mixed, B/G/N Mixed or A/N mixed mode, only N-mode can be effective.
- WDS only supports security mode “open” or “WEP”, but N-mode doesn’t support WEP.
- When “N mode” is configured as RF-type, then the security mode, using WDS, would be set to “Open”.
- When WDS with “WEP” shall be used, RF-type must be set to B,G, B/G Mixed or A.

Version 1.9.2 Build 18030716

Released: April 2018

- First release