

Technical change to RS 32IO 2W F R S module

Dear Madam or Sir,

The products listed below are subject to a product change and will be supplied in a modified revision. Please pass this product information on to your employees and, if needed, to your customers. All modifications mentioned have been made to support our ongoing commitment to continual improvement and ongoing product development.

1. Initial situation


Article on Section 5 was delivered in the past with LPK SI fuse holders and 1302800000 BL QB 10 Jumpers.



RS 32IO 2W F R S Interface (w/ LPK SI fuse holder)

2. Technical change

Based on continuous improvement, the LPK SI fuse holders mentioned in Section 1 will be replaced by LPA SI fuse holders. Furthermore, 1302800000 BL QB 10 Jumpers will be replaced by 1472200000 LPA QB 2 Jumpers.

Old version	New version
LPK SI fuse holder 	LPA SI fuse holder 
1302800000 Jumper 	1472200000 Jumper 

3. Reason for change

Obsolescence of LPK SI fuse holder and blocking of 1302800000 BL QB 10 Jumper.

4. Availability

Once the stock of either the LPK SI fuse holder or the 1302800000 Jumper is finished, new productions will be done with the new modifications detailed above.

5. Affected parts

9441570000 RS 32IO 2W F R S

6. Data

PCN-number: 20231222

Date of publishing: 22-12-2023

This document has indefinite validity from today

For further questions, or in case any additional assistance or information is needed, please contact your sales office directly. All contacts for sales representatives are available here: www.weidmueller.com/contact

Best regards

Marc Bosch

Product Support

Weidmüller – Your partner in Industrial Connectivity
We look forward to sharing ideas with you – **Let's connect.**

Weidmüller Interface GmbH & Co. KG
Klingenbergstraße 16, 32758 Detmold, Germany