



The manufacturer
may use the mark:



Revision 3.0 October 16, 2026
Surveillance Audit Due
November 1, 2029



Certificate / Certificat Zertifikat / 合格証

Weidmüller 070902 C001

exida hereby confirms that the:

Pulse Isolator
ACT20X-(2)HDI-(2)SDO-S/P
ACT20X-(2)HDI-(2)SDO-RNO-S/P
ACT20X-(2)HDI-(2)SDO-RNC-S/P
Device version 2

Weidmüller Interface GmbH CO KG
Detmold, Germany

Have been assessed per the relevant requirements of:

IEC 61508 : 2010 Parts 1 - 3

and meets requirements providing a level of integrity to:

Systematic Capability: SC 2 (SIL 2 Capable)

Random Capability: Type B Route 2_H Device

**PFD_{AVG} and Architecture Constraints
must be verified for each application**

Safety function:

The Pulse Isolators provides EX-isolation of digital signals, on/off converter for NAMUR sensors or mechanical switches between hazardous areas and safe areas.

Application restrictions:

The unit must be properly designed into a Safety Instrumented Function per the requirements in the Safety Manual.



Evaluating Assessor

Certifying Assessor

Systematic Capability: SC 2 (SIL 2 Capable)**Random Capability: Type B Route 2_H Device**

**PFD_{AVG} and Architecture Constraints
must be verified for each application**

Pulse Isolators

ACT20X-(2)HDI-(2)SDO-S/P

ACT20X-(2)HDI-(2)SDO-RNO-S/P

ACT20X-(2)HDI-(2)SDO-RNC-S/P

**Weidmüller Interface
GmbH CO KG**

Detmold, Germany

Systematic Capability :

The products has met manufacturer design process requirements of Safety Integrity Level (SIL) 2. These are intended to achieve sufficient integrity against systematic errors of design by the manufacturer.

A Safety Instrumented Function (SIF) designed with these products must not be used at a SIL level higher than the statement without "prior use" justification by end user or diverse technology redundancy in the design.

Random Capability:

The SIL limit imposed by the Architectural Constraints must be met for each subsystem.

**Summary for the Pulse Isolators ACT20X-(2)HDI-(2)SDO-S/P,
ACT20X-(2)HDI-(2)SDO-RNO-S/P and ACT20X-(2)HDI-(2)SDO-RNC-S/P:**

IEC 61508:2010 Failure rates in FIT*

	λ_{Safe}	λ_{DD}	λ_{DU}
Relay output	108	85	55
Opto output	112	85	46

*FIT= 1 failure / 10⁹ hours

SIL Verification:

The Safety Integrity Level (SIL) of an entire Safety Instrumented Function (SIF) must be verified via a calculation of PFD_{AVG} considering redundant architectures, proof test interval, proof test effectiveness, any automatic diagnostics, average repair time and the specific failure rates of all products included in the SIF. Each subsystem must be checked to assure compliance with minimum hardware fault tolerance (HFT) requirements.

The following documents are mandatory parts of this certificate:

Weidmüller 24-02-017-C R001 Assessment Report ACT20X V1R0

Safety manual ACT20X-(2)HDI-(2)SDO V0.2

Safety manual ACT20X-(2)HDI-(2)SDO-RNx V0.2



80 N Main St
Sellersville, PA 18960