

PCB Layout Update for Pin Header Families SV 7.62 Hybrid and SV-SMT 7.62 Hybrid

Dear Madam or Sir,

Product adaptations serve the purpose of continuous product and/or process improvement. The listed products are delivered in a modified version. Please pass this product information on to your employees and, if needed, to your customers.

1. General overview

Type of notification: ☐ PCN ☐ PDN ☒ Short-term action

Short-term action due to:

- | | |
|--|---|
| ☐ Software / Firmware Bugfix | ☐ Short term delivery stop by supplier |
| ☐ Short term recall by supplier | ☐ Force majeure |
| ☐ Product improvement with customer benefit | ☒ other |

2. Technical changes

As part of an internal review, we have identified that the PCB layout for pin header families SV 7.62 Hybrid and SV-SMT 7.62 Hybrid is different to our published PCB layout in the catalog and the data sheet.

Wrong PCB Layout	Correct PCB Layout

3. Availability

Production of the SV 7.62 Hybrid and SV-SMT 7.62 Hybrid families has been based exclusively on the updated PCB layout.

4. Affected parts

A list of the affected articles can be found in the appendix.

We are very sorry for all the inconveniences caused and doing everything to adjust this product change as smooth as possible without big influence on delivery times and general functions.

For further questions please contact your sales office directly. All contacts for sales representatives are available here:
<http://www.weidmueller.com/contact>

Einzelheiten zu diesen und anderen Produktänderungen finden Sie auch in unserem Support Center, indem Sie dem Link folgen: <https://support.weidmueller.com/support-center>

Best regards

Product Management

Weidmüller Interface GmbH & Co. KG

Klingenbergstraße 26 | 32758 Detmold | Germany
www.weidmueller.com