

**Firmware change-log of new features and bug fixes of the u-remote field bus coupler:  
2661310000 UR20-FBC-IEC61162-450****Firmware updating Information:**

An update of the firmware can be done via the embedded web server. A description of the firmware update can be found in the u-remote web server manual on the Weidmüller website: [www.weidmueller.com](http://www.weidmueller.com)

<b>Version 01.02.00</b>	<b>Hardware Version 01.xx.xx</b>	<b>Release date: March, 2022</b>
-------------------------	----------------------------------	----------------------------------

Minor bugfixes and software improvements for performance

<b>Version 01.01.00</b>	<b>Hardware Version 01.xx.xx</b>	<b>Release date: March, 2020</b>
-------------------------	----------------------------------	----------------------------------

**New supported modules:**

- UR20-4AI-RTD-DIAG
- UR20-4AI-TC-DIAG
- UR20-4RO-CO-255
- UR20-4RO-SSR-255
- UR20-4DI-2W-230V-AC

**Bug Fixes:**

- Fixed issue regarding fallback page during firmware update

**Known issue:**

Web server sometimes freezes after downgrade from firmware 02.09.00 until browser cache gets cleared

<b>Version 01.00.00</b>	<b>Hardware Version 01.xx.xx</b>	<b>Release date: July, 2019</b>
-------------------------	----------------------------------	---------------------------------

- First released version