

## Technical change to HDC RockStar® ModuPlug MHX 3

Dear Madam or Sir,

The below listed articles will be supplied in a modified revision. Please pass this product information on to your employees and, if needed, to your customers. All modifications are performed for reasons of product improvements.





### 1. Initial situation

Increased customer requirement for the HDC RockStar® ModuPlug MHX 3 module.

### 2. Technical change

- Geometric optimization of the contact chamber to increase the contact fit.
- The mounting force of the crimp contacts has been increased.

#### Product images



**3. Reason for change**

- Product improvement
- Increased standard requirement according to NFF 61030

**4. Availability**

The changeover will take place successively, after the previous material variants have been sold off.

**5. Affected parts**

1429340000	HDC MHX 3 MC
1429350000	HDC MHX 3 FC

**6. Data**

PCN-number:	PCN-PB72-20190910-00-A
Date of publishing:	2019, September 10
Duration of validity:	Until further notice
Revision number:	00-A

We are very sorry for any inconveniences caused and are doing everything possible to implement this product change as smoothly as possible, without any big influences on delivery times and general functions.

For further questions please contact your sales office directly. All contacts for sales representatives are available here: [www.weidmueller.com/contact](http://www.weidmueller.com/contact)

Best regards

Product Management

Weidmüller Interface GmbH & Co. KG  
Klingenbergstraße 26, 32758 Detmold, Germany

**Weidmüller** – Your partner in Industrial Connectivity  
We look forward to sharing ideas with you – **Let's connect.**