

## Technical change to FreeCon Active Repeater

Dear Madam or Sir,

the products listed below are subject to a product change and will be supplied in a modified revision. Please pass this product information on to your employees and, if needed, to your customers. All modifications mentioned have been made to support our ongoing commitment to continual improvement and ongoing product development.

### **1. Initial situation**

LED "BF" does not light up if there is no connection to the controller.

### **2. Technical change**

According to the AIDA specification, the "BF" LED now lights up if no connection to the controller is established.

Old version	New version
<b>FW 1.40.01 (PI Certificate Z12385)</b>	<b>FW 1.41.06</b>

### **3. Reason for change**

LED display was not AIDA compliant

### **4. Availability**

March 2019

### **5. Affected parts**

2581810000 IE-CDR-V14MRJ/VAPM-C

We hope that the changes will benefit your business and will not affect you in any significant way and apologise in case of any inconvenience caused. Please rest assured that we will do everything possible to achieve this product change as smoothly as possible with minimum or no business disruption.

For further questions or if you need any additional assistance or information, please contact your local sales office directly. All contacts for sales representatives are available here: <http://www.weidmueller.com/contact>

Details of this and any other product changes can also be found on our web page by following the link:  
<http://www.weidmueller.com/int/service/online-support-and-downloads/product-change-notification>

Best regards

Product Management

Weidmüller Interface GmbH & Co. KG  
Klingenbergsstraße 16, 32758 Detmold, Germany

**Weidmüller** – Your partner in Industrial Connectivity  
We look forward to sharing ideas with you – **Let's connect.**