

Technical change for FrontCom Vario

Dear Madam or Sir,

the products listed below are subject to a product change and will be supplied in a modified revision. Please pass this product information on to your employees and, if needed, to your customers. All modifications mentioned have been made to support our ongoing commitment to continual improvement and ongoing product development.

1. Initial situation

- Use of socket outlet with color coding and fixed recess

2. Technical change

- There is no color coding on the back of the sockets and a mechanical recess is also made. This becomes visible when using the plug provided for this purpose.



3. Reason for change

- Change of manufacturer to standardize the market

4. Availability

- January 2022

5. Affected parts

- 2007230000

6. Data

- PCN-PB47-20211129-00-A
- 29.11.2021

We hope that the changes will benefit your business and will not affect you in any significant way and apologise in case of any inconvenience caused. Please rest assured that we will do everything possible to achieve this product change as smoothly as possible with minimum or no business disruption.

For further questions or if you need any additional assistance or information, please contact your local sales office directly. All contacts for sales representatives are available here: <http://www.weidmueller.com/contact>

Details of this and any other product changes can also be found on our web page by following the link shown below

<http://www.weidmueller.com/int/service/online-support-and-downloads/product-change-notification>

Best regards

Product Management

Weidmüller Interface GmbH & Co. KG
Klingenbergstraße 16, 32758 Detmold, Germany

Weidmüller – Your partner in Industrial Connectivity
We look forward to sharing ideas with you – **Let's connect.**