

Firmware change-log of new features and bug fixes of the u-remote field bus coupler: 2799510000 UR20-FBC-EIP-ECO

Firmware updating Information:

An update of the firmware can be done via the embedded web server. A description of the firmware update can be found in the u-remote web server manual on the Weidmüller website: www.weidmueller.com

| Version 01.04.00 | Hardware Version 01.xx.xx | Release date: February, 2025 |
|-------------------------|----------------------------------|-------------------------------------|
|-------------------------|----------------------------------|-------------------------------------|

New features:

- Improved hot swap properties - requires UR20-AUX-VSYS as last module on the station

| Version 01.03.00 | Hardware Version 01.xx.xx | Release date: October, 2024 |
|-------------------------|----------------------------------|------------------------------------|
|-------------------------|----------------------------------|------------------------------------|

New supported modules:

- 2920830000 - UR20-3EM-400V-AC-CT1A
- 2920840000 - UR20-3EM-400V-AC-CT5A
- 2920850000 - UR20-3EM-400V-AC-RC
- 2920860000 - UR20-3EM-400V-AC-333MV

Bug fixes:

- Fixed implausible readings of module parameter via class 0x67
- WebApp: Fixed swapping of process data according to data format setting in hardware config file (L5X)
- Fixed BF LED behaviour in modular mode when using only an explicit connection
- Coupler doesn't reboot when the service "Set Attribute All" for class 0x67 "Module parameter" is used
- Input process data set to "0" for applications with power feed modules in case the module is powered off
- WebApp: Fixed display of substitute values for UR20-2PWM-I-2.5A-2DI-P

| Version 01.02.00 | Hardware Version 01.xx.xx | Release date: February, 2024 |
|-------------------------|----------------------------------|-------------------------------------|
|-------------------------|----------------------------------|-------------------------------------|

Bug fixes:

- Gateway class (100), attribute "Module parameter" (115) gets initialized correctly

| Version 01.01.01 | Hardware Version 01.xx.xx | Release date: August, 2022 |
|-------------------------|----------------------------------|-----------------------------------|
|-------------------------|----------------------------------|-----------------------------------|

New supported modules:

- 2697910000 - UR20-2PWM-I-2.5A-2DI-P

Bug fixes:

- Editing parameter "IP configuration" and editing the IP address at the same time sometimes no longer resets the IP address

| Version 01.00.00 | Hardware Version 01.xx.xx | Release date: December, 2021 |
|-------------------------|----------------------------------|-------------------------------------|
|-------------------------|----------------------------------|-------------------------------------|

- First released version

Caution:

- This firmware requires "u-mation Device Configurator" version $\geq 1.3.1$