

Weidmüller Interface GmbH & Co. KG
Klingenbergstraße 16
32758 Detmold
Tel. +49 5231 14-0
Fax +49 5231 14-29 20 83
info@weidmueller.com
www.weidmueller.com




HX 10 mm²
Crimpkontakt

HX 10 mm²
Crimping contact

Montage / Assembly

1.



2.

HX 10 mm² Kontakt vercrimpt mit
CTIN CM 3.6 9205440000
Locator Pos. 3
Crimpmaß 3,1 mm

HX 10 mm² Crimp contact with
CTIN CM 3.6 9205440000
Locator Pos. 3
Crimping size 3.1 mm



3.

HDC HQ 4/2 FC
1003160000

HDC HQ 4/2 MC
1003170000




Leiter nur in Pos. 1 und 4 anschließen
Use only pos.1 and 4

Verwendung nur in Kunststoff-Gehäusen / Only for use in plastic housings

Demontage / Disassembly

1.



Leiter abschneiden
cut wire

2.



Kabelisolierung abziehen
remove insulation

3.



Removal Tool HX 1002990000
einführen und
Kontakt raus ziehen

Removal Tool HX 1002990000
Insert tool and
pull out the contact