

Technical change to passive M23 FixCon distribution boxes

Dear Madam or Sir,

the passive distribution boxes with FixCon quick connection and vertical M23 connector will be changed.
Please pass on this Product Change Notification (PCN) to your employees and, if applicable, to your customers.

1. General overview

Type of change: ☒ **short-term** (executed within the next 6 months)
☐ **normal** (executed after 6 months)

Short-term action due to:

- | | |
|---|--|
| <input type="checkbox"/> Software or firmware bugfix | <input type="checkbox"/> Delivery stop by supplier |
| <input type="checkbox"/> Short-term recall by supplier | <input type="checkbox"/> Force majeure |
| <input checked="" type="checkbox"/> Product improvement | <input type="checkbox"/> other |

Short-term action due to:


Use of lead-free M23 connector with quick-connect contour



2. General information

The M23 connector was previously designed as a leaded version with a standard M23 thread. As part of the product change, a lead-free M23 connector (without RoHS exemption according to 6c) is being used.

3. Change details

Previously, a lead-containing material was used for the M23 connector of the affected article. As part of the changeover, this will be switched to a lead-free material. Furthermore, the M23 connector in the new design has a modified contour, which enables the connection of M23 connectors with quick connection. The change results in deviations in the dimensions from the existing article. All other technical specifications remain identical.



Preexisting design	New design
	

4. Affected parts

1512950000 - SAI-4-S 5P FC NPN
1847920000 - SAI-8-S 4P FC
1847960000 - SAI-4-S 4P FC
1847970000 - SAI-4-S 5P FC
1848040000 - SAI-8-S 5P FC
1861580000 - SAI-8-S 5P CNOMO

5. Timeline

This letter is to inform you that the change is expected to be implemented in production with immediate effect. Mixed deliveries may occur due to stock levels.

We hope that the changes will benefit your business and will not affect you in any significant way. We apologise in case of any inconvenience caused. Please rest assured that we will do everything possible to achieve this product change as smoothly as possible with minimum or no business disruption.

For further questions please contact your sales office directly. All contacts for sales representatives are available here: <https://www.weidmueller.com/contact>

Details of this and any other product changes can also be found in our Support Center by following the link: <https://support.weidmueller.com/support-center/popular-resources/product-change-notifications>

Best regards

Product Management

Weidmüller Interface GmbH & Co. KG
Klingenbergstraße 26 | 32758 Detmold | Germany
www.weidmueller.com

in    