

## Changelog of new features and bug fixes of PRO COM IO-LINK

### PRO COM IO-Link (2587360000)

#### **Software Version Number (SVN) 2.5.0**

**Release date: March 2022**

##### **New features and changes:**

- Add new features to PROtop for IODD Version 1.7.0
- Changed Boolean interpretation to 0= false and 1-255= true
- Changed length of input and output voltage and output current for topGUARD/ PROtop from 4 byte to 2 byte
- Changed access of temperature from register 260 SUB 0 to register 260 SUB 1
- Changed access of temperature counter from register 261 SUB 0 and register 262 SUB 0 to register 261 SUB 1 and 261 SUB 2
- Added Index 284 – PROtop Rated Value Current Limit Output
- Added Index 286 – PROtop Output Voltage Current Select
- Added Index 299 – PROtop AOP Value
- Added Index 318 – PROtop Check O-Ring Function
- Added Index 325 – PROtop Switch Off Settings
- Added Index 326 – PROtop Switch Off Times
- Added Command 162 – PROtop Reload Command
- Added Command 170 – PROtop Check O-Ring Command
- Added Command 171 – PROtop Save Rated Value Current Limit Output Command
- Added Command 174 – 177 – PROtop Switch On Command

##### **New supported modules:**

- PROtop DC series
- PROtop2 UW series

##### **Bug Fixes:**

- Fixed timing problem of read only parameter with topGUARD
- Fixed wrong positive response if an invalid parameter was sent
- Fixed rare problems of events

##### **Known Issues:**

- Index 260 not readable with PROtop with specific SVN versions (see document “compatibility of PRO COM”)

#### **Software Version Number (SVN) 2.4.1**

**Release date: January 2020**

- First released version