

## Technical change to 9447100000/1311790000

Dear Madam or Sir,

the above listed articles will be supplied in a modified revision. Please pass this product information on to your employees and, if needed, to your customers. All modifications are performed for reasons of product improvements.

### 1. Initial situation

Based on continuous improvement of our products and to provide an smother connection between our interfaces 9447100000/1311790000 in combination with cables 7789387xxx we are going to replace the existing PCB connector from Wurth to FCI manufacturer

### 2. Technical change

Change the Wurth connector (Black) by FCI connector (light grey).



### 3. Reason for change

Improve the connection between 7789387xxx and 9447100000/1311790000.

### 4. Availability

The production of the new version started in cw49/2019. Afterwards the stock change is an ongoing process.

## 5. Affected parts

RSM-16 C 1CO Z	9447100000
RS 16IO 2W H Z	1311790000

We are very sorry for all the inconveniences caused and doing everything to adjust this product change as smooth as possible without big influence on delivery times and general functions.

For further questions please contact your sales office directly. All contacts for sales representatives are available here: [www.weidmueller.com/contact](http://www.weidmueller.com/contact)

Best regards

Product Management

Weidmüller Interface GmbH & Co. KG  
Klingenbergstraße 16, 32758 Detmold, Germany

**Weidmüller** – Your partner in Industrial Connectivity  
We look forward to sharing ideas with you – **Let's connect.**