

Technical change to FrontCom Vario Single Frame

Dear Madam or Sir,

the products listed below are subject to a product change and will be supplied in a modified revision. Please pass this product information on to your employees and, if needed, to your customers. All modifications mentioned have been made to support our ongoing commitment to continual improvement and ongoing product development.

1. Initial situation

The knob for closing the cover is out of plastic and the handling is not optimal.

2. Technical change

The material of the button was changed to metal, the contour enlarged.



Previous version



new version

3. Reason for change

The robustness and durability is improved, the operation (closing / opening) facilitates.

4. Availability

June 2019

5. Affected parts

1450510000 IE-FC-SFP-KNOB

1450530000 IE-FC-SFM-KNOB

We hope that the changes will benefit your business and will not affect you in any significant way and apologise in case of any inconvenience caused. Please rest assured that we will do everything possible to achieve this product change as smoothly as possible with minimum or no business disruption.

For further questions or if you need any additional assistance or information, please contact your local sales office directly. All contacts for sales representatives are available here: <http://www.weidmueller.com/contact>

Details of this and any other product changes can also be found on our web page by following the link:
<http://www.weidmueller.com/int/service/online-support-and-downloads/product-change-notification>

Best regards

Product Management

Weidmüller Interface GmbH & Co. KG
Klingenbergsstraße 16, 32758 Detmold, Germany

Weidmüller – Your partner in Industrial Connectivity
We look forward to sharing ideas with you – **Let's connect.**