

**EDS file change-log of new features, bug fixes of the  
u-remote field bus coupler: 1334920000 UR20-FBC-EIP**

**EDS file for Hardware version 02.xx.xx:**

**ethip-v1.7-weidmueller-ur20-fbc-EIP-HW2-1334920000.eds**

**EDS file for Hardware version 01.xx.xx:**

**ethip-v1.7-weidmueller-ur20-fbc-EIP-HW1-1334920000.eds**

---

**Version 1.7****Release date: July 2025****New supported modules:**

- 2819690000 - UR20-4COM-IO-LINK-V2
- 3096630000 - SAI-AU-M8-SB-8DO-2A-V2
- 3096500000 - SAI-AU-M8-SB-8DI-V2
- 3096510000 - SAI-AU-M8-SB-8DIO-V2
- 3096490000 - SAI-AU-M12-SB-8DO-2A-V2
- 3096470000 - SAI-AU-M12-SB-8DI-V2
- 3096480000 - SAI-AU-M12-SB-8DIO-V2

---

**Version 1.6****Release date: March 2020****New feature:**

- New assemblies 111 – 114 for support of new web server feature “Hardware config file (.l5x)” (HW2 only)

---

**Version 1.5****Release date: December 2017****New feature:**

- Additional coupler parameter „HTTPS settings” (HW2 only)

---

**Version 1.4****Release date: May 15, 2017****Bug fix:**

- Improved compatibility with various Engineering software

---

**Version 1.2****Release date: October 06, 2016****New feature:**

- Additional coupler parameter “Output behaviour on idle”

---

**Version 1.1****Release date: February 02, 2016****New feature:**

- Added new Configuration Assembly 123

---

**Version 1.0****Release date: October 21, 2014**

First released version